
Document ID: 2083321 Page 1 of 2

2009 Chevrolet Aveo | Aveo, Wave, G3, Barina (VIN S/T) Service Manual | Driver Information and Entertainment Cellular, Entertainment, and Navigation | Repair Instructions | Document ID: 2083321

## **Communication Interface Module Replacement**

**Removal Procedure** 

Warning: Refer to **Battery Disconnect Warning** in the Preface section.






Note: The vehicle communication interface module (VCIM) has a specific set of unique numbers that tie the module to each vehicle. These numbers, the 10-digit station identification and the 11-digit electronic serial number, are used by the National Cellular Network and OnStar® to identify the specific vehicle. Because these numbers are tied to the vehicle identification number of the vehicle, you must never exchange these parts with those of another vehicle.

- 1. Disconnect the battery ground cable.
- 2. Disconnect the electrical connectors from the communication interface module which is located on the bottom of the driver seat.
- 3. Slide the driver seat forward.
- 4. Remove the bolts (1) and remove the communication interface module cover (2) from the seat rear side.

## **Installation Procedure**

© 2012 General Motors Corporation. All rights reserved.

Page 2 of 2 Document ID: 2083321





1. Position the vehicle communication interface module (2) in the vehicle.

**Caution:** Refer to <u>Fastener Caution</u> in the Preface section.

- 2. Install the bolts (1) and tighten to 3 N·m (27 lb in).
- 3. Restore the driver seat position.
- 4. Connect vehicle communication interface module electrical connectors.

**Warning:** Refer to <u>Battery Disconnect Warning</u> in the Preface section.

5. Connect the battery ground cable.