
2008 Cadillac CTS
 CTS (VIN D) Service Manual
 Driver Information and Entertainment

 Cellular, Entertainment, and Navigation
 Repair Instructions
 Document ID: 1978224

## **Communication Interface Module Replacement**



Callout	Component Name			
Preliminary Procedure				
Remove the rear window shelf trim panel. Refer to <u>Rear Window Panel Trim Replacement</u> .				
	Communication Interface Module Nut			
1	Notice: Refer to Fastener Notice in the Preface section.			
	<b>Tighten</b> 9 N·m (80 lb in)			
	Communication Interface Module			
2	Procedure			
	Disconnect the electrical connections.			

	If replacing the communication interface module be sure to transfer Bluetooth Antenna, if equipped.
	For programming and set up, refer to Control Module References

© 2011 General Motors Corporation. All rights reserved.