


2004 Cadillac SRX
Fig. 2: Right Rear Of Vehicle Behind Trim Panel Component View
Courtesy of GENERAL MOTORS CORP.



© 2011 Mitchell Repair Information Co., LLC.